

Fig. 5




Fig. 7




Fig. 8






Fig. 6








Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17






Fig. 18






Fig. 21

Fig. 22




Fig. 23




FIG. 25 is a perspective view of the vehicle wash apparatus with the boom in a retracted position. The boom 244 is shown in a retracted position, and the spray gun 248 is shown in a retracted position. The spray gun 248 is shown in a retracted position, and the spray gun 248 is shown in a retracted position.




Fig. 25




Fig. 26




Fig. 27








Fig. 28






Fig. 33






Fig. 39




Fig. 40




Fig. 37




Fig. 38




Fig. 42





Fig. 41






Fig. 45




Fig. 46